

April 15, 1992

Sarah K. Odland
CDM Federal Programs Corp.
111 Fulton Street, Suite 710
New York, New York 10038


Re: Aerial Photographs
Tutu Service Station Investigation
St. Thomas, U.S. Virgin Islands

Dear Ms. Odland:

Enclosed are aerial photographs of St. Thomas, U.S. Virgin Islands. The aerial photographs were used for our fracture trace analysis for the Tutu Service Station Investigation. The methods and results of the fracture trace analysis were presented in Geraghty & Miller's report dated April 10, 1992 "Technical Memorandum I, Tutu Service Station Investigation, St. Thomas, U.S. Virgin Islands." Table 1 presents a packing list of the aerial photographs enclosed. Please maintain the integrity and quality of the photographs. Kindly return these aerial photos when your review is completed. If you have any questions or comment, please call.


Sincerely,

GERAGHTY & MILLER, INC.



Thomas V. Danahy

Senior Scientist/Project Manager



Daniel A. Nachman/TVD

Daniel A. Nachman
Vice President/Project Officer

Enclosures

c: 

Ana Gloria Ramos, TEIC

CM/mtb

#PR01301-#2/041592.ltr

TUT 006 1813

Table 1. Packing List of Aerial Photographs, Tutu Service Station Investigation, St. Thomas, U.S. Virgin Islands.

Date, Size, and Type of Aerial Photo	State and County Code	Exposure Number
February 7, 1971		
10" x 10" B/W Paper 1:20,000	PCFD	101-103
January 29, 1954		
9" x 9" B/W Paper 1:28,000	GSYM	158-160 173-175

TD:kj
PR013.01-wp3/041592.lt4