


ATTACHMENT A

COMPARISON OF
GERAGHTY AND MILLER'S AND CDM FPC'S
INTERPRETATION OF FRACTURE TRACES
IN THE IMMEDIATE VICINITY
OF THE TUTU WELL FIELD SITE




SOURCE USGS QUADRANGLE EASTERN ST THOMAS V.I. (1984)

CDM FEDERAL PROGRAMS CORPORATION

Tutu Well Field Site
Work Assignment C02048

Figure 1

Geraghty and Miller Interpretation of
Fracture Traces in Technical Memorandum I
April 10, 1992



SOURCE: USGS QUADRANGLE EASTERN ST. THOMAS, V.I. (1984)

CDM FEDERAL PROGRAMS CORPORATION

Tutu Well Field Site
Work Assignment C02048

Figure 2

CDM FPC Interpretation of
Fracture Traces in the Area of the Site